# **BookletChart**<sup>TM</sup>

# NORA THOSPHERIC ROMMINSTRATION OF COMMINSTRATION OF COMMINSTRATION

# Intracoastal Waterway – Little Egg Harbor to Cape May NOAA Chart 12316

A reduced-scale NOAA nautical chart for small boaters When possible, use the full-size NOAA chart for navigation.



- Complete, reduced-scale nautical chart
- Print at home for free
- Convenient size
- Up-to-date with Notices to Mariners
- Compiled by NOAA's Office of Coast Survey, the nation's chartmaker

	5	Appro 6	ximate Page In	dex 1 to 10	MUCCA CONTINUE  WILLIAM TO CAPE MAY  ATTAINED  ATTAINED
			13	14	15
16	17	18	19	20	21

# Published by the National Oceanic and Atmospheric Administration National Ocean Service Office of Coast Survey

<u>www.NauticalCharts.NOAA.gov</u> 888-990-NOAA

# What are Nautical Charts?

Nautical charts are a fundamental tool of marine navigation. They show water depths, obstructions, buoys, other aids to navigation, and much more. The information is shown in a way that promotes safe and efficient navigation. Chart carriage is mandatory on the commercial ships that carry America's commerce. They are also used on every Navy and Coast Guard ship, fishing and passenger vessels, and are widely carried by recreational boaters.

# What is a BookletChart<sup>™</sup>?

This BookletChart is made to help recreational boaters locate themselves on the water. It has been reduced in scale for convenience, but otherwise contains all the information of the full-scale nautical chart. The bar scales have also been reduced, and are accurate when used to measure distances in this BookletChart. See the Note at the bottom of page 5 for the reduction in scale applied to this chart.

Whenever possible, use the official, full scale NOAA nautical chart for navigation. Nautical chart sales agents are listed on the Internet at http://www.NauticalCharts.NOAA.gov.

This BookletChart does NOT fulfill chart carriage requirements for regulated commercial vessels under Titles 33 and 44 of the Code of Federal Regulations.

# **Notice to Mariners Correction Status**

This BookletChart has been updated for chart corrections published in the U.S. Coast Guard Local Notice to Mariners, the National Geospatial Intelligence Agency Weekly Notice to Mariners, and, where applicable, the Canadian Coast Guard Notice to Mariners. Additional chart corrections have been made by NOAA in advance of their publication in a Notice to Mariners. The last Notices to Mariners applied to this chart are listed in the Note at the bottom of page 7. Coast Pilot excerpts are not being corrected.

For latest Coast Pilot excerpt visit the Office of Coast Survey website at <a href="http://www.nauticalcharts.noaa.gov/nsd/searchbychart.php?chart=123">http://www.nauticalcharts.noaa.gov/nsd/searchbychart.php?chart=123</a> <a href="http://www.nauticalcharts.noaa.gov/nsd/searchbychart.php?chart=123">16</a>



(Selected Excerpts from Coast Pilot)
Beach Haven Inlet (39°30.0'N., 74°15.1'W.),
17 miles south-southwestward of Barnegat
Inlet, is unmarked. Numerous wrecks and
shoal spots are at the entrance. Due to
changing conditions of the channel, boatmen
are advised to seek local knowledge prior to
entering.

The entrance to Beach Haven Inlet should not be mistaken for Little Egg Inlet, which is close southward. **Beach Haven Coast Guard** 

**Station** is inside the barrier beach, 3.2 miles north of Beach Haven Inlet. **Little Egg Inlet** (39°29.0'N., 74°17.5'W.), 19 miles south-southwestward of Barnegat Inlet and close southward of Beach Haven Inlet, is used considerably by local pleasure and fishing boats. Depth over the bar is ample for any vessel that can navigate the inside waters, but in very

heavy weather breakers form all the way across the bar. The inlet channels and shoreline are constantly changing; the entrance is well marked, but the buoys are not charted because they are frequently shifted in position. In 2007, an unmarked partially submerged wreck was reported at about 39°29'09.6"N., 74°17'31.2"W.; caution is advised. **Absecon Inlet**, 8.7 miles southwestward of Little Egg Inlet, is on the northeast side of Atlantic City, the largest resort on the New Jersey coast. The inlet is protected at the entrance by jetties; a revetment extends along the Atlantic City side of the inlet. Small-craft facilities are available at a hotel marina on the southwest side of the inlet. The channel through the inlet is well marked to the entrance to Clam Creek and to a junction with the New Jersey Intracoastal Waterway, 1 mile and 1.9 miles, respectively, above the inlet entrance south jetty. In 2007, the controlling depth was 9.5 feet to Clam Creek; thence in 2009, 3.0 feet in Clam Creek entrance channel with shoaling to lesser depths in the north half of the channel, with depths of 10.9 to 15.0 feet in the basin. Current velocities up to 6 knots reported in the channel. Weather.-The climate of Atlantic City is principally continental in character; however, the moderating influence of the Atlantic Ocean is apparent throughout the year. As a result, the summers are relatively cooler and winters milder than elsewhere at the same latitude. Land and sea breezes often prevail. The weather tends to remain comparatively mild late into the fall, but warming is retarded in the spring. January is the coldest month and July the warmest. The average annual temperature for Atlantic City is 53.7°F (12.1°C). The average January temperature is 31.7°F (-0.2°C) and the average July temperature is 75.3°F (24.1°C). Temperatures in excess of 100°F (37.8°C) have occurred in each month, June through August, and temperatures in excess of 90°F (32.2°C) have occurred in each month, April through October. Each month has recorded below freezing temperatures except June, July, and August and each month, December through February, has recorded temperatures below 0°F (-17.8°C). The warmest temperature on record for Atlantic City is 106°F (41.1°C) recorded in June 1969 while the coldest temperature on record is -11°F (-23.9°C) recorded in February 1979. Precipitation, on the average, is moderate and well distributed throughout the year, with June the driest month and August the wettest. The average annual precipitation for Atlantic City is 41 inches (1041 mm). Thunderstorms are mostly a warm season phenomena. The bulk of winter precipitation results from storms which move northeasterly along or close to the coast. Snowfall, at about 17 inches (432 mm) per year, is considerably less than elsewhere at the same latitude, and does not remain long on the ground. Snow has fallen in each month, October through May. The greatest 24-hour snowfall was 16.6 (421.6 mm) recorded in February 1979. Ice storms are relatively infrequent. (See Appendix B for Atlantic City climatological table.) Atlantic City, on the south side of Absecon Inlet, is a base for a large fleet of fishing vessels and pleasure craft. The city has highway, rail, and air connections with the mainland; highways lead to the coastal towns northward and southward.

**Atlantic City Coast Guard Station** is on the north side of the entrance to Clam Creek.

**Clam Creek**, on the south side of Absecon Inlet, has its marked entrance 1 mile northwestward of the south jetty light. The creek includes **Gardner Basin**, **Snug Harbor**, and **Delta Basin** on its southerly side, and the small-boat basin of the State marina on its northerly side.

U.S. Coast Guard Rescue Coordination Center 24 hour Regional Contact for Emergencies

RCC Norfolk Commander

5th CG District Norfolk, VA

(575) 398-6231

# HEIGHTS

Heights in feet above Mean High Water.



NOTE B

Channel is marked by private seasonal aids

# NOTE B

Channel is marked by private seasonal aids

# NOTE C

LITTLE EGG HARBOR

White and orange daybeacons are private aids

# NOTE G

Shoaling has been reported from 39°23'09" N 74°43'27" W to Mays Landing.

# STORM WARNING DISPLAYS

Storm warning signals are displayed from nasts of Police Patrol Boats while underwa-ilong the New Jersey coast and the Inland

# CAUTION

Oyster grounds are marked by stakes and flags. Submerged broken stakes become dangerous obstructions to small craft.

# CAUTION

Improved channels shown by broken lines are subject to shoaling, particularly at the edges.

# CAUTION

Mariners are warned to stay clear of the protective riprap surrounding navigational light structures shown thus:

# ABSECON CREEK ---

The controling mid-channel depth at mean ower low water from the mouth of the creek to Absecon highway bridge was reported to be 51/2 feet.

# RADAR REFLECTORS

Radar reflectors have been placed on many floating aids to navigation. Individual radar reflector identification on these aids has beer omitted from this chart.

# SUBMARINE PIPELINES AND CABLES

Charted submarine pipelines and submarin cables and submarine pipeline and cable area are shown as:

Additional uncharted submarine pipelines an submarine cables may exist within the area of this chart. Not all submarine pipelines and sub marine cables are required to be buried, ar those that were originally buried may hav become exposed. Mariners should use extrem caution when operating vessels in depths water comparable to their draft in areas whe water comparable to trieff draft in areas when pipelines and cables may exist, and whe anchoring, dragging, or trawling. Covered wells may be marked by lighted of

unlighted buoys

All craft should avoid areas where the skin divers flag, a red square with a diagonal white stripe, is displayed.

# CAUTION

Limitations on the use of radio signals as aids to marine navigation can be found in the U.S. Coast Guard Light Lists and National Geospatial-Intelligence Agency Publication 117. Radio direction-finder bearings to commercial

broadcasting stations are subject to error and should be used with caution. Station positions are shown thus:

(Accurate location) o(Approximate location)

# RACING BUOYS

Racing buoys within the limits of this chart are not shown hereon. Information may be obtained from the U.S. Coast Guard District Offices as racing and other private buoys are not all listed in the U.S. Coast Guard Light List.

Boundary lines of fish trap areas are show

Submerged piling may exist in these areas.

# SUBMARINE PIPELINES AND CABLES

Charted submarine pipelines and submarine cables and submarine pipeline and cable areas

Additional uncharted submarine pipelines an submarine cables may exist within the area of this chart. Not all submarine pipelines and sub marine cables are required to be burie those that were originally buried may become exposed. Mariners should use e caution when operating vessels in depths of water comparable to their draft in areas where pipelines and cables may exist, and wher

anchoring, dragging, or trawling. Covered wells may be marked by lighted o

# CAUTION

Temporary changes or defects in aids to navigation are not indicated on this chart. See Local Notice to Mariners.

During some winter months or when endangered by ice, certain aids to navigation are replaced by other types or removed. For details see U.S. Coast Guard Light List.

# CAUTION

Small craft should stay clear of large commercial and government vessels even if small craft have the right-of-way.

# CAUTION

Mariners are warned to stay clear of the protective riprap surrounding navigational light structures shown thus:

# INTRACOASTAL WATERWAY

Project Depths

6 feet Manasquan Inlet, NJ to Ottens Harbor, NJ; 10 feet Ottens Harbor, NJ to Richardson Channel, NJ; 12 feet Richardson Channel, NJ to

The controlling depths are published period-cally in the U.S. Coast Guard Local Notice to

# WARNING

The prudent mariner will not rely solely on any single aid to navigation, particularly on floating aids. See U.S. Coast Guard Light List and U.S. Coast Pilot for details.

# CALITION

Improved channels shown by broken lines are subject to shoaling, particularly at the edges

# CAUTION

Temporary changes or defects in aids to navigation are not indicated on this chart. See Local Notice to Mariners.

Local Notice to Mariners.

During some winter months or when endangered by ice, certain aids to navigation are replaced by other types or removed. For details see U.S. Coast Guard Light List.

# CAUTION

# BASCULE BRIDGE CLEARANCES

For bascule bridges, whose spans do not open to a full upright or vertical position, unlimited vertical clearance is not available for the entire charted horizontal clearance

# INTRACOASTAL WATERWAY Project Depths

6 feet Manasquan Inlet, NJ to Ottens Harbor, NJ; 10 feet Ottens Harbor, NJ to Richardson Channel, NJ; 12 feet Richardson Channel, NJ to Cape May Inlet, NJ. The controlling depths are published periodically in the U.S. Coast Guard Local Notice to

# Distances

The Waterway is indicated by a magenta line Mileage distances shown along the Waterway are in Statute Miles, southward from Manasquan Inlet (12324, Side A) and indicated thus:

Tables for converting Statute Miles to Inter-

national Nautical Miles are given in U.S. Coast

Courses are TRUE and must be CORRECTED for any variation and compass deviation.

# INTRACOASTAL WATERWAY AIDS

Table of Selected Chart Notes

The U.S. Aids to Navigation System is designed for use with nautical charts, and the exact meaning of an aid to navigation may not be clear unless the appropriate chart is consulted.

Aids to navigation marking the Intracoastal Waterway exhibit unique yellow symbols to distinguish them from aids marking other water-

When following the Intracoastal Waterway southward from Manasquan Inlet to Cape May, NJ, aids with yellow triangles should be kept on yellow squares should be kept on the port side of the vessel.

yellow squares another of the vessel. A horizontal yellow band provides no lateral information, but simply identifies aids to navigation as marking the Intracoastal Waterway.

All lights and lighted buoys marking the Intra-

coastal Waterway on this chart show a flash every four seconds, unless otherwise specified.

The aids marking tributary channels, in general, are maintained by the state of New Jersey.

Fixed and floating obstructions, some submerged, may exist within the magenta tinted bridge construction area. Mariners are advised to proceed with caution.

# HORIZONTAL DATUM

The horizontal reference datum of this chart is North American Datum of 1983 (NAD 83), which for charting purposes is considered equivalent to the World Geodetic System 1984 (WGS 84). Geographic positions referred to the North American Datum of 1927 must be corrected an average of 0.417" northward and 1.432" eastward to agree with this chart.

## HURRICANES AND TROPICAL STORMS

Hurricanes, tropical storms and other major storms may cause considerable damage to marine structures, aids to navigation and moored vessels, resulting in submerged debris in unknown locations.

Charted soundings, channel depths and shoreline may not reflect actual conditions following these storms. Fixed aids to navigation may have been damaged or destroyed. Buoys may have been moved from their charted positions, damaged, sunk, extinguished or otherwise made inoperative. Mariners should not rely upon the position or operation of an aid to navigation Wrecks and submerged obstructions may have been displaced from charted locations. Pipelines may have become uncovered or moved.

Mariners are urged to exercise extreme caution and are requested to report aids to navigation discrepancies and hazards to navigation to the nearest United States Coast Guard

# CAUTION BASCULE BRIDGE CLEARANCES

For bascule bridges, whose spans do not open to a full upright or vertical position, unlimited vertical clearance is not available for the entire charted horizontal clearance. entire charted horizontal clearance.

# AUTHORITIES

Hydrography and topography by the National Ocean Service, Coast with additional data from the Corps of Engineers, U.S. Coast Guard and State of New Jersey, Bureau of Navigation.

# CAUTION

# FISH TRAP AREAS AND STRUCTURES

Mariners are warned that numerous uncharted duck blinds and fishing structures, some submerged, may exist in the fish trap areas. Such structures are not charted unless known to be permanent

Regulations to assure clear passage to and through dredged and natural channels, and to established landings, are prescribed by the Corps of Engineers in the Code of Federal Regulations.

Where definite limits have not been prescribed, the location of fishing structures is restricted only by the regulations.

The state of the s THA GALLAS THE TAIL T ERV.

CADACITY TONS TAL CANOL ROW HOOD RANK CHARTER HOUSE SAIL RIPERO TO THE TOP OF THE PARTY RUL MOTOR RADIO SMALL CRAFT FACILITY D C WI H BT DG MORRISON'S MARINA 8 5 30 TSLP 11 BEACH HAVEN YACHT CLUB MARINA ВΕ FL TSLP C WI GH BT DG 4 ВЕ C WI GH BT DG 14 3.5 С TSLP HOLGATE MARINA н FL D C WI H 22/ DEEBOLD BOATYARD 8 20 ВΕ ΤP М DG BT DG 60 45 38 AMMERMAN'S ATLANTIC CITY MARIN 10 5 ВΕ TS P C WI C WI GH BT DG 51E SEAVIEW HARBOR MARINA TSLP WD C WI H T DG 65 GARDEN STATE YACHT SALES 6 BE TS P 5 5 В HME 35 P WD MARINE MAX 70 HACKNEY'S BOAT YARD 6 6 ВΕ НМ 20 TPDCWIHBTG SEA VILLAGE MARINA 72 4 4 ВΕ HME 20 М Н FL TSLP WD C WI H BT G ВΕ HMF TSLP D C WI 79A BASS RIVER YACHTING CENTER 6 6 GREAT BAY MARINA ME TS P WD C WI GH BT DG 81 5 5 BE 20 С TUCKERTON MARINA SERVICE CENTER TS P WD C WI H BT G 95 Α 4 4 BE 25 SHELTERED COVE MARINA 5 10 BE S НМЕ TS P D C WI GH BT 102A ALL SEASONS MARINA 4 4 BE N HMR 35 TS P D C WI H BT DG 116 COMMODORE BAY CLUB MARINA В 8 4 BE нм 5 TS P C WI DG 118 AVALON POINT MARINA 10 10 B E HMR 70 TS P D C WI BT DG 123 STONE HARBOR MARINA В 10 4 BE HMB 25 TS P WD C WI DG 10 145 HINCH MARINA В 5 5 BE S H TS P D C WI H BT G WI H BT DG 146 BREE-ZEE-LEE YACHT BASIN 4 2 BE S HMR 50 T P D В 146E HARBOR VIEW MARINA 4 10 BME нм 30 TS P WD C WI GH BT DG В 148 CANYON CLUB 6 6 B E 60 TSLP WD C WI H BT DG 149 UTSCH'S MARINA 8 8 BE нм 35 TSLP D C WI GH BT DG CRM CHS F FL TSLP C WI GH BT DG 152 SOUTH JERSEY MARINA В 8 8 BE С 153 ROSEMAN BOAT YARD 5 HMB FLC TSLP WD C WI GH BT DG 154 CAPE MAY MARINE 10 6 BE S HMR 77 TS P WD C WI

THE LOCATIONS OF THE ABOVE PUBLIC MARINE FACILITIES ARE SHOWN ON THE CHART BY MAGENTA NUMBERS AND LEADERS.

THE TABULATED TAPPROACH-REET (REPORTED): IS THE DEPTH AVAILABLE FROM THE NEAREST NATURAL OR DREDGED CHANNEL TO THE FACILITY.

THE TABULATED "PUMPA-OUT STATION" IS DEFINED AS FACILITIES AVAILABLE FOR PUMPING OUT BOAT HOLDING TANNS.

# HURRICANES AND TROPICAL STORMS

Hurricanes, tropical storms and other major storms may cause considerable damage to marine structures, aids to navigation and moored vessels, resulting in submerged debris in unknown locations.

Charted soundings, channel depths and shoreline may not

reflect actual conditions following these storms. Fixed aids to navigation may have been damaged or destroyed. Buoys may have been moved from their charted positions, damaged, sunk, extinguished or otherwise made inoperative. Mariners should not rely upon the position or operation of an aid to navigation Wrecks and submerged obstructions may have been displaced from charted locations. Pipelines may have become uncovered

Mariners are urged to exercise extreme caution and are requested to report aids to navigation discrepancies and hazards to navigation to the nearest United States Coast Guard

Fixed and floating obstructions, some ubmerged, may exist within the magenta tinted bridge construction area. Mariners are advised to proceed with caution.

# INTRACOASTAL WATERWAY

# Project Depths

6 feet Manasquan Inlet, NJ to Ottens Harbor, NJ; 10 feet Ottens Harbor, NJ to Richardson Channel, NJ; 12 feet Richardson Channel, NJ to Cape May Inlet, NJ. The controlling depths are published period-ically in the U.S. Coast Guard Local Notice to

# Distances

The Waterway is indicated by a magenta line. Mileage distances shown along the Waterway are in Statute Miles, southward from Manasquan Inlet (12324, Side A) and indicated thus:

Tables for converting Statute Miles to Inter-

national Nautical Miles are given in U.S. Coast

Courses are TRUE and must be CORRECTED for any variation and compass deviation

# INTRACOASTAL WATERWAY AIDS

The U.S. Aids to Navigation System is designed for use with nautical charts, and the exact meaning of an aid to navigation may not be clear unless the appropriate chart is consulted. Aids to navigation marking the intracoastal Waterway exhibit unique yellow symbols to

distinguish them from aids marking other water

When following the Intracoastal Waterway southward from Manasquan Inlet to Cape May, NJ, aids with yellow triangles should be kept on

A horizontal yellow band provides no lateral information, but simply identifies aids to navigation as marking the Intracoastal Waterway.

All lights and lighted buoys marking the Intra-

coastal Waterway on this chart show a flash every

four seconds, unless otherwise specified.


The aids marking tributary channels, in general, are maintained by the state of New Jersey.




Dashes (- - -) located in datum colun tide predictions, and tidal current pre (Sep 2012)

with leaders and refer





Note: Chart grid lines are aligned with true north.



# **FACILITIES** marine facilities are shown by large magenta numbers to the facility tabulation.

TIDAL INFORMATI	ON

		Height referred to datum of soundings (MLLW)			
	(LAT/LONG)	Mean Higher High Water	Mean High Water	Mean Low Water	
		feet	feet	feet	
on	(39°33'N/74°15'W)	2.5	2.3	0.1	
	(39°32'N/74°23'W)	3.7	3.3	0.1	
horofare	(39°26'N/74°22'W)	4.1	3.8	0.1	
	(39°21'N/74°25'W)	4.6	4.2	0.2	
	(39°20'N/74°29'W)	4.6	4.2	0.2	
	(39°19'N/74°32'W)	4.3	3.9	0.1	
	(39°13'N/74°39'W)	4.3	4.0	0.2	
	(38°59'N/74°49'W)	4.9	4.5	0.2	
	(38°58'N/74°58'W)		5.0	0.2	

imns indicate unavailable datum values for a tide station. Real-time water levels redictions are available on the Internet from http://tidesandcurrents.noaa.gov.

# NO-DISCHARGE ZONE, 40 CFR 140

NO-DISCHARGE ZONE, 40 CFR 140
Under the Clean Water Act, Section 312, all vessels operating within a No-Discharge Zone (NDZ) are completely prohibited from discharging any sewage, treated or untreated, into the waters. All vessels with an installed marine sanitation device (MSD) that are navigating, moored, anchored, or docked within a NDZ must have the MSD disabled to prevent the overboard discharge of sewage (treated or untreated) or install a holding tank. Regulations for the NDZ are contained in the U.S. Coast Pilot. Additional information concerning the regulations and requirements may be obtained from the Environmental Prolection Agency (EPA) web site: http://www.epa.gov/oww/occans/regulatory/vessel\_swage/. owow/oceans/regulatory/vessel\_sewage/

# PRINT-ON-DEMAND CHARTS


PHINT-ON-DEMAND CHARTS

NOAA and its partner, OceanGrafix, offer this chart
updated weekly by NOAA for Notices to Mariners and
critical corrections. Charts are printed when ordered using
rint-on-Demand technology. Now Editions are available 2-8
weeks before their release as traditional NOAA charts. Ask your
chart agent about Print-on-Demand charts or contact: NOAA at
http://cos.data.ncd.noaa.gov/id/s/inquiry.aspx, or
OceanGrafix at 1-877-56CHART or http://www.oceangrafix.com

FISH TRAP ARE

Mariners are warned that fishing structures, some subm Such structures are not charted Regulations to assure clear natural channels, and to estab Corps of Engineers in the Code Definite limits of fish trap areas, and those limits are sho Where definite limits have fishing structures is restricted of

Within the 12-nautical mile Territoria some Federal laws apply. The Three louter limit of the territorial sea, is retain limit of the other laws. The 9-nautical m of Florida, Texas, and Puerto Rico, and most cases the inner limit of Federal fi jurisdiction of the states. The 24-nautic mile Exclusive Economic Zone were Unless fixed by treaty or the U.S. Sup to modification.



# CAUTION

# FISH TRAP AREAS AND STRUCTURES

Mariners are warned that numerous uncharted duck blinds and fishing structures, some submerged, may exist in the fish trap areas. Such structures are not charted unless known to be permanent.

Regulations to assure clear passage to and through dredged and natural channels, and to established landings, are prescribed by the Corps of Engineers in the Code of Federal Regulations.

Definite limits of fish trap areas have been established in some areas, and those limits are shown thus:

Where definite limits have not been prescribed, the location of fishing structures is restricted only by the regulations.

# NOTE X

Within the 12-nautical mile Territorial Sea, established by Presidential Proclamation, some Federal laws apply. The Three Nautical Mile Line, previously identified as the outer limit of the territorial sea, is retained as it continues to depict the jurisdictional limit of the other laws. The 9-nautical mile Natural Resource Boundary off the Gull coast infinition in bother laws. The 9-habitical mile islands resource solutionly of the control of Florida, Texas, and Puerto Rico, and the Three Nautical Mile Line elsewhere remain in most cases the inner limit of Federal fisheries jurisdiction and the outer limit of the jurisdiction of the states. The 24-nautical mile Contiguous Zone and the 200-nautical mile Exclusive Economic Zone were established by Presidential Proclamation. Unless fixed by treaty or the U.S. Supreme Court, these maritime limits are subject to modification.

# WARNING

The prudent mariner will not rely solely on any single aid to navigation, particularly on floating aids. See U.S. Coast Guard Light List and U.S. Coast Pilot for details

# CAUTION

Improved channels shown by broken lines are subject to shoaling, particularly at the edges.

# CAUTION

Mariners are warned to stay clear of the protective riprap surrounding navigational light structures shown thus:

# AIDS TO NAVIGATION

Consult U.S. Coast Guard Light List for supplemental information concerning aids to navigation.

# CAUTION


Temporary changes or defects in aids to


navigation are not indicated on this chart. See Local Notice to Mariners. During some winter months or when endan-greed by ice, certain aids to navigation are replaced by other types or removed. For details see U.S. Coast Guard Light List.

ART 12318 Formerly 826-SC, 1st E 19 74018 38 n buoys 35 21 Ŋ 21 page 13 Joins 13 (12) (12) (12) Joins page 12 کی کے



<del>1:40,000</del> | Miles Printed at reduced scale. See Note on page 5. Note: Chart grid lines are aligned Nautical 1/2 0 Yards 1000 0 1000 with true north. 2000 3000 4000 5000





# NAUTICAL CHART 12316 INTRACOASTAL WATERWAY

# LITTLE EGG HARBOR TO CAPE MAY



Chart 12316 35th Ed., Oct. / 12 ■
Corrected through NM Oct. 20/12, LNM Oct. 16/12

Published at Washington, D.C.
U.S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SERVICE
COAST SURVEY

MERCATOR PROJECTION AT SCALE 1:40,000 NORTH AMERICAN DATUM OF 1983 (WORLD GEODETIC SYSTEM 1984) SOUNDINGS IN FEET AT MEAN LOWER LOW WATER

Additional information can be obtained at nauticalcharts.noaa.gov





HEIGHTS
Heights in feet above Mean High Water.

SUPPLEMENTAL INFORMATION

Consult U.S. Coast Pilot 3 for important supplemental information.


# HORIZONTAL DATUM

The horizontal reference datum of this chart is North American Datum of 1983 (NAD 83), which for charting purposes is considered equivalent to the World Geodetic System 1984 (WGS 84). Geographic positions referred to the North American Datum of 1927 must be corrected an average of 0.417" northward and 1.432" eastward to agree with this chart.


# AUTHORITIES


Hydrography and topography by the National Ocean Service, Coast Survey, with additional data from the Corps of Engineers, U.S. Coast Guard, and State of New Jersey, Bureau of Navigation.


This nautical chart has been designed to promote safe navigation. The National Ocean Service encourages users to submit corrections, additions, or comments for improving this chart to the Chief, Marine Chart Division (N/CS2), National Ocean Service, NOAA, Silver Spring, Maryland 20910-3282.





—Joins page 15 **₌** 





























Note: Chart grid lines are aligned with true north.










with true north.

















Printed at reduced scale. SCALE 1:40,000 See Note on page 5.

Note: Chart grid lines are aligned with true north.









# VHF Marine Radio channels for use on the waterways:

**Channel 6** – Inter-ship safety communications.

Channel 9 – Communications between boats and ship-to-coast.

Channel 13 – Navigation purposes at bridges, locks, and harbors.

Channel 16 – Emergency, distress and safety calls to Coast Guard and others, and to initiate calls to other

vessels. Contact the other vessel, agree to another channel, and then switch.

Channel 22A – Calls between the Coast Guard and the public. Severe weather warnings, hazards to navigation and safety warnings are broadcast here. Channels 68, 69, 71, 72 and 78A – Recreational boat channels.

**Getting and Giving Help** — Signal other boaters using visual distress signals (flares, orange flag, lights, arm signals); whistles; horns; and on your VHF radio. You are required by law to help boaters in trouble. Respond to distress signals, but do not endanger yourself.

# **Distress Call Procedures**

- Make sure radio is on.
- Select Channel 16.
- Press/Hold the transmit button.
- Clearly say: "MAYDAY, MAYDAY, MAYDAY."
- Also give: Vessel Name and/or Description; Position and/or Location; Nature of

Emergency; Number of People on Board.

- · Release transmit button.
- Wait for 10 seconds If no response Repeat MAYDAY call.

HAVE ALL PERSONS PUT ON LIFE JACKETS!



NOAA Weather Radio All Hazards (NWR) is a nationwide network of radio stations broadcasting continuous weather information directly from the nearest National Weather Service office. NWR broadcasts official Weather Service warnings, watches, forecasts and other hazard information 24 hours a day, 7 days a week.

http://www.nws.noaa.gov/nwr/

# **Quick References**

Nautical chart related products and information — http://www.nauticalcharts.noaa.gov

Online chart viewer — <a href="http://www.nauticalcharts.noaa.gov/mcd/NOAAChartViewer.html">http://www.nauticalcharts.noaa.gov/mcd/NOAAChartViewer.html</a>

Report a chart discrepancy — http://ocsdata.ncd.noaa.gov/idrs/discrepancy.aspx

Chart and chart related inquiries and comments — http://ocsdata.ncd.noaa.gov/idrs/inquiry.aspx?frompage=ContactUs

Chart updates (LNM and NM corrections) — http://www.nauticalcharts.noaa.gov/mcd/updates/LNM\_NM.html

Coast Pilot online — http://www.nauticalcharts.noaa.gov/nsd/cpdownload.htm

Tides and Currents — http://tidesandcurrents.noaa.gov

Marine Forecasts — http://www.nws.noaa.gov/om/marine/home.htm

National Data Buoy Center — http://www.ndbc.noaa.gov/

NowCoast web portal for coastal conditions — http://www.nowcoast.noaa.gov/

National Weather Service — http://www.weather.gov/

National Hurrican Center — http://www.nhc.noaa.gov/

Pacific Tsunami Warning Center — http://ptwc.weather.gov/

Contact Us — http://www.nauticalcharts.noaa.gov/staff/contact.htm



For the latest news from Coast Survey, follow @nauticalcharts



This Booklet chart has been designed for duplex printing (printed on front and back of one sheet). If a duplex option is not available on your printer, you may print each sheet and arrange them back-to-back to allow for the proper layout when viewing.

